




Fig. 1






# VG4000<sup>+</sup> Block Diagram



VG 4000<sup>+</sup> ARCHITECTURE

Fig. 2



# CSM Block Diagram





Fig. 3

64,66,68 A



# System Controller I/O Card




Fig. 4

# Quad OC3 Block Diagram





Fig. 5

9





# ViaJet A40x Block Diagram





Fig. 7a



# ViaWay A406





Fig. 7b





# Typical Digital Set-Top Box




Fig. 7C


800

Fig. 8

8/2







FOIA b 7 - D

# Connection Management





Fig. 11



# CATV/Broadcast Management




Fig. 12

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☐ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☒ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**